

Eaton Corporation  
Innovation Center  
26201 Northwestern Highway  
Southfield, Michigan 48076  
(248) 226-6200

---



October 13, 2010

Mr. John Huron  
Senior Research Engineer  
Chevron Oronite Company  
4502 Centerview, Suite 210  
San Antonio, TX 78228

Dear Mr. Huron

We have reviewed the bench test data and the 35VQ25 (Eaton ATS 373 and ASTM D6973) pump test results you provided on OR 15699A, ISO VG32. A blend of 0.66% wt. OLOA 26008A, 0.2% wt. Viscoplex 1-156 in 65.18% wt. RLOP 220R and 33.96% wt. RLOP 100R.

It is our opinion that OR 15699A, ISO VG32 meets the anti-wear requirements of the hydraulic fluid recommendation sheet for Vickers products for mobile and industrial hydraulic systems according to Brochure 694.

Sincerely

A handwritten signature in dark ink, appearing to read "Thelma Marougy", is written over a light blue horizontal line.

Thelma Marougy  
Lubricant Specialist  
Power and Motion Control Division  
Hydraulics Group

TM/cd

Copy: Eaton: J. LeClair, T. Degler, A. George